

FIG. 1




FIG. 1




FIG. 3




FIG. 5




FIG. 6





FIG. 7



F I G. 9

SETTING	THRESHOLD RANGE	
1 1 1 1 1 1 1 1	2 5 5	M A X
1 1 0 1 1 1 1 1	2 2 3	
1 0 1 1 1 1 1 1	1 9 1	
1 0 0 1 1 1 1 1	1 5 9	
0 1 1 1 1 1 1 1	1 2 7	
0 1 0 1 1 1 1 1	9 5	
0 0 1 1 1 1 1 1	6 3	
0 0 0 1 1 1 1 1	3 1	
0 0 0 0 0 0 0 0	0	M I N

FOUO-SEN-500





FIG. 12

